Cooling Cap

Model #17001

Note: Misty Mate recommends that you pre-was h (with warm water and soap) and allow the unit to dry completely before the first use in order to prevent the material from bleeding.

Directions:

- Submerge the Cooling Cap in a bowl of cold water for 3-5 minutes in order to ensure maximum absorbency.
- Remove the Cooling Cap from the bowl and lightly squeeze out any excess water – do not twist or wring. Distribute the cooling crystals evenly throughout.
- Place the Cooling Cap on your head. Tie ends loosely behind your head for a comfortable fit.

Note: For prolonged use, repeat steps every 1- 2 hours.

CAUTION: IN THE EVENT THE PRODUCT TEARS OR BREAKS, PLEASE DISPOSE. DO NOT INGEST.

Cover: 100% Cotton

Fill: Acroleic Acid, Was hing Soda, Acrylamide (polyacrylamide), NN — Methy-lene — Bis — Acrylamide, Potassi um Pers ulfate, Hydrosulfite of Sodium.

DESIGNED IN THE USA - MANUFACTURED IN CHINA
WWW.MISTYMATE.COM